


DATE 5/14/2003

TEAM C

BUILDING (location)

C-14-08

BINGOL LISESI (BLDG B)



|   |    |    |     |
|---|----|----|-----|
| N | 38 | 53 | 139 |
| E | 40 | 30 | 317 |

STRUCTURE (Description)

Dual system

No. STORIES ABOVE GROUND

4

HEIGHT

3.50 m

PICTURE #'S

DAMAGE LEVEL

RC Structure: M. Walls:

Severe


Severe

PERMANENT DRIFT

OBSERVATIONS

The buildings are separate, but there is no gap between them.  
There are shear and flexure cracks on beams and joints.

PLAN VIEW



All units are in cm.

Masonry wall thickness 30 cm for exterior walls

25 cm for interior walls

Make sure you include:

Overhangs  Col. Dim.  RC Wall Dim.  M. Wall Dim.